


3 Phase 4 Wire Distribution Board

Neutral Connections


4 Pole Isolator Main Breaker

Earth Connections



Three Phase Breaker to supply voltages to Meter

PX-5 Enclosure fitted with IC-5 Meter



Auxiliary (Fused) Voltage Supply

2 Wires are supplied to loop into L1 Voltage and Neutral Terminals at the Meter

Plastic Conduit (25mm)

Neutral Current Transformer Optional
Only required if measuring Neutral Current

Current Transformers

Mains Cable