


3 Phase 4 Wire Distribution Board

Neutral Connections

4 Pole Isolator Main Breaker

Earth Connections




Current Transformers

Mains Cable

Three Phase Breaker to supply voltages to Meter

PX-5 Enclosure fitted with IC-5 Meter



Auxiliary (Fused) Voltage Supply

2 Wires are supplied to loop into L1 Voltage and Neutral Terminals at the Meter

Plastic Conduit (25mm)

Neutral Current Transformer Optional
Only required if measuring Neutral Current